



Overview: Part of spill impact on 12" Adibawa – Okordia Pipeline Right of Way at Ikarama. Picture was taken during Joint Investigation of 18th September 2015.



Close-up: Hacksaw cut on 12" Adibawa – Okordia Pipeline at Ikarama. Picture was taken during Joint Investigation of 18th September 2015.