



Overview: Part of Spill Impact on 6" Seibou Bulkline4 Right of Way at Azagbene. Picture was taken during Joint Investigation of 1<sup>st</sup> September 2015.



Close-up: Hacksaw cut on 6" Seibou Bulkline4 at Azagbene. Picture was taken during Joint Investigation of 26<sup>th</sup> April 2016.