




Overview: Part of spill impact around KoloCreek Well13 Wellhead at Imiringi. Picture was taken during Joint Investigation of 11<sup>th</sup> August 2015.



Close-up: KoloCreek Well13 Wellhead at Imiringi. Picture was taken during Joint Investigation of 11<sup>th</sup> August 2015.