




**Overview:** Part of spill impact on 28" Bomu-Bonny Trans Niger Pipeline Right of Way at Anyaminima /Oloma. Picture was taken during Joint Investigation of 17<sup>th</sup> December 2015.



**Close-up:** Illegal fitting on 28" Bomu-Bonny Trans Niger Pipeline at Anyaminima /Oloma. Picture was taken during Joint Investigation of 17<sup>th</sup> December 2015.