



Overview: Part of spill impact on 20" Otumara-Escravos Pipeline Right of Way at Ogidigben. Picture was taken during Joint Investigation of 23rd December 2015.



Close-up: Illegal fitting on 20" Otumara-Escravos Pipeline at Ogidigben. Picture was taken during Joint Investigation of 23rd December 2015.