



Overview: Part of spill impact on 20" Rumuekpe – Nkpoku Pipeline Right of Way at Omukpobu-Ibaa. Picture was taken during Joint Investigation of 7<sup>th</sup> January 2016.



Close-up: Hacksaw cut on 20" Rumuekpe – Nkpoku Pipeline at Omukpobu-Ibaa. Picture was taken during Joint Investigation of 7<sup>th</sup> January 2016.