



Overview: Part of spill impact on Afam Well27 8" Flowline Right of Way at Ayamandoki. Picture was taken during Joint Investigation of 7th January 2016.



Close-up: Illegal fitting on Afam Well27 8" Flowline at Ayamandoki. Picture was taken during Joint Investigation of 7th January 2016.