



Overview: Part of spill impact on 8" Etelebou – KoloCreek Pipeline Right of Way at Etegwe/Okutukutu. Picture was taken during Joint Investigation of 22nd January 2016.



Close-up: Hacksaw cut on 8" Etelebou – KoloCreek Pipeline at Etegwe/Okutukutu. Picture was taken during Joint Investigation of 22nd January 2016.