



Overview: Part of spill impact on 20" Otumara-Escravos Pipeline Right of Way at Ugboegungun. Picture was taken during Joint Investigation of 7<sup>th</sup> February 2015.



Close-up: Illegal fitting on 20" Otumara-Escravos Pipeline at Ugboegungun. Picture was taken during Joint Investigation of 7<sup>th</sup> February 2015.