



Overview: Part of spill impact on 28" Nkpoku-Bomu Pipeline Right of Way at Kpoghor/Gbam. Picture was taken during Joint Investigation of 11th February 2015.



Close-up: Illegal fitting on 28" Nkpoku-Bomu Pipeline at Kpoghor/Gbam. Picture was taken during Joint Investigation of 11th February 2015.