



Overview: Part of spill impact on Belema Well10L/S Wellhead Right of Way at Belema. Picture was taken during Joint Investigation of 24th February 2015.



Close-up: Position of missing Control Unit on Belema Well10L Wellhead at Belema. Picture was taken during Joint Investigation of 24th February 2015.



Close-up: Position of missing Control Unit on Belema Well10S Wellhead at Belema. Picture was taken during Joint Investigation of 24th February 2015.