



Overview: Part of spill impact on 24" Nembe Creek Pipeline Right of Way at Adamakiri. Picture was taken during Joint Investigation of 3<sup>rd</sup> of March 2015.



Close-up: Illegal fitting on 24" Nembe Creek Pipeline at Adamakiri. Picture was taken during Joint Investigation of 3<sup>rd</sup> of March 2015.