



Overview: Part of spill impact on 8" Assa-Rumuekpe Pipeline Right of Way at Imogu. Picture was taken during Joint Investigation of 2nd of March 2015.



Close-up: Drilled hole on 8" Assa-Rumuekpe Pipeline at Imogu. Picture was taken during Joint Investigation of 6th of March 2015.