



		E 6.350336	Date 2015/01/20
		N 4.431176	Time 13:17:57 +01:00
		Altitude -21.500 M	Speed 0.87 KPH

Overview: Part of spill impact on Nembe Well 40L Wellhead Flowline at Ikovia. Picture was taken during Joint Investigation of 20th January 2015.



		E 6.351008	Date 2015/01/20
		N 4.431491	Time 13:42:14 +01:00
		Altitude 10.600 M	Speed 0.02 KPH

Close-up: Spill due to pinhole leak on Nembe Well 40L Wellhead Flowline at Ikovia. Picture was taken during Joint Investigation of 20th January 2015.