



Close-up: Illegal fitting on 28" Bomu-Bonny Trans Niger Pipeline at Bodo West. Picture was taken during Joint Investigation of 3<sup>rd</sup> February 2015.