



		E 5.919428	Date 2015/02/10
		N 4.828561	Time 14:28:31 (UTC)
		Altitude 16.500 M	Speed 2.39 KPH

**Overview:** Part of spill impact on Seibou Well2S Flowline Right of Way at Gbanraun. Picture was taken during Joint Investigation of 10<sup>th</sup> of February 2015.



**Close-up:** Outward tear on Seibou Well2S Flowline at Gbanraun. Picture was taken during Joint Investigation of 13<sup>th</sup> of March 2015.