



Overview: Part of spill impact on 20" Otumara – Escravos Pipeline Right of Way at Ogidigben. Picture was taken during Joint Investigation of 4th July 2015.



Close-up: Illegal fitting on 20" Otumara – Escravos Pipeline at Ogidigben. Picture was taken during Joint Investigation of 4th July 2015.