



Overview: Part of spill impact on 28" Bomu-Bonny Pipeline Right of Way at Owokiri. Picture was taken during Joint Investigation of 8th July 2015.



Close-up: Illegal fitting prior to temporary repair on 28" Bomu-Bonny Pipeline at Owokiri. Picture was taken during Joint Investigation of 8th July 2015.



Close-up: Illegal fitting after temporary repair by blind flanging on 28" Bomu-Bonny Pipeline at Owokiri. Picture was taken during Joint Investigation of 8th July 2015.