




Overview: Part of spill impact on 10" Diebu Creek – Nun River Pipeline Right of Way at Oporoma. Picture was taken during Joint Investigation of 13th July 2015.



Close-up: Hacksaw cut (A) on 10" Diebu Creek – Nun River Pipeline at Oporoma. Picture was taken during Joint Investigation of 13th July 2015.



Overview: Hacksaw cut (B) on 10" Diebu Creek – Nun River Pipeline at Oporoma. Picture was taken during Joint Investigation of 14th July 2015.



Close-up: Hacksaw cut (C) on 10" Diebu Creek – Nun River Pipeline at Oporoma. Picture was taken during Joint Investigation of 14th July 2015.