



Overview: Part of spill impact on 28" Bomu-Bonny Pipeline at Bodo-City. Picture was taken during Joint Investigation of 29th July 2015.



Close-up: Illegal fitting on 28" Bomu-Bonny Pipeline at Bodo-City. Picture was taken during Joint Investigation of 29th July 2015.