


**Overview:** Part of spill impact on 20" Otumara - Escravos Pipeline at Ogidigben. Picture was taken during Joint Investigation of 29<sup>th</sup> July 2015.



**Close-up:** Illegal fitting on 20" Otumara - Escravos Pipeline at Ogidigben. Picture was taken during Joint Investigation of 29<sup>th</sup> July 2015.