




Overview: Part of spill impact on 16" NunRiver - KoloCreek Pipeline at Angiama. Picture was taken during Joint Investigation of 22nd July 2015.



Close-up: Hacksaw cut on 16" NunRiver - KoloCreek Pipeline at Angiama. Picture was taken during Joint Investigation of 22nd July 2015.