



Overview: Part of spill impact on 24" Trans-Escravos Pipeline Right of Way at Burutu. Picture was taken during Joint Investigation of 4th August 2015.



Close-up: Illegal fitting on 24" Trans-Escravos Pipeline at Burutu. Picture was taken during Joint Investigation of 4th August 2015.