



Overview: Part of spill impact on Adibawa Well 16T Wellhead Right of Way at Edagberi. Picture was taken during Joint Investigation of 29th July 2015.



Close-up: Spill point on Adibawa Well 16T Wellhead at Edagberi. Picture was taken during Joint Investigation of 29th July 2015.