



Overview: Part of spill impact on 28" Nkpoku-Bomu Pipeline Right of Way at Ejamah-Ebubu. Picture was taken during Joint Investigation of 7th June 2015.



Close-up: Illegal fitting on 28" Nkpoku-Bomu Pipeline at Ejamah-Ebubu. Picture was taken during Joint Investigation of 7th June 2015.