



Overview: Part of spill impact on 28" Nkpoku-Bomu Pipeline Right of Way at B-Dere. Picture was taken during Joint Investigation of 8th June 2015.



Close-up: Leaking and non-leaking drilled holes from previous incident on 28" Nkpoku-Bomu Pipeline at B-Dere. Picture was taken during Joint Investigation of 8th June 2015.