



Overview: Part of spill impact on 18" Assa-Rumuekpe Pipeline Right of Way at Elele/Alimini-Ihuaba. Picture was taken during Joint Investigation of 26th June 2015.



Close-up: Drilled hole on 18" Assa-Rumuekpe Pipeline at Elele/Alimini-Ihuaba. Picture was taken during Joint Investigation of 26th June 2015.