



Overview: Part of spill impact around Obigbo Well10T Wellhead at Umudinor. Picture was taken during Joint Investigation of 30th June 2015.



Close-up: Tampered wellhead on Obigbo Well10T Wellhead at Umudinor. Picture was taken during Joint Investigation of 30th June 2015.