



Overview: Part of spill impact on 20" KoloCreek – Rumuekpe Pipeline Right of Way at Odau. Picture was taken during Joint Investigation of 24<sup>th</sup> June 2015.



Close-up: Illegal fitting on 20" KoloCreek – Rumuekpe Pipeline at Odau. Picture was taken during Joint Investigation of 24<sup>th</sup> June 2015.