



Overview: Part of spill impact on 24" Trans-Escravos Pipeline Right of Way at Sokebolou. Picture was taken during Joint Investigation of 23rd June 2015.



Close-up: Illegal fitting on 24" Trans-Escravos Pipeline at Sokebolou. Picture was taken during Joint Investigation of 29th June 2015.