



Close-up: Concrete cast found on 12" Imo River – Ogale Pipeline at Uzuaku. Picture was taken during Joint Investigation of 2<sup>nd</sup> July 2015.



Close-up: Illegal fittings on 12" Imo River – Ogale Pipeline at Uzuaku. Picture was taken during Joint Investigation of 2<sup>nd</sup> July 2015.