



Overview: Part of spill impact on 28" Nkpoku – Bomu Pipeline Right of Way at B-Dere. Picture was taken during Joint Investigation of 1<sup>st</sup> July 2015.



Close-up: Illegal fitting on 28" Nkpoku – Bomu Pipeline at B-Dere. Picture was taken during Joint Investigation of 1<sup>st</sup> July 2015.