



Overview: Part of spill impact on 6" Tunu – Kanbo Well4L Flowline Right of Way at Agbidiama. Picture was taken during Joint Investigation of 16th November 2015.



Close-up: Cut section of flowline on 6" Tunu – Kanbo Well4L Flowline at Agbidiama. Picture was taken during Joint Investigation of 20th November 2015.