



Overview: Part of spill impact on 18" Assa-Rumuekpe Trans Niger Pipeline Right of Way at Egbeda. Picture was taken during Joint Investigation of 14th of March 2015.



Close-up: Illegal fitting on 18" Assa-Rumuekpe Trans Niger Pipeline at Egbeda. Picture was taken during Joint Investigation of 14th of March 2015.