



Overview: Part of spill impact on 28" Bomu-Bonny Pipeline Right of Way at BodoWest. Picture was taken during Joint Investigation of 10<sup>th</sup> of March 2015



Close-up: Illegal fitting on 28" Bomu-Bonny Pipeline at BodoWest. Picture was taken during Joint Investigation of 10<sup>th</sup> of March 2015.