




Overview: Part of spill impact on 10" Diebu Creek – Nun River Pipeline Right of Way at Oporoma. Picture was taken during Joint Investigation of 26<sup>th</sup> of April 2015.



Close-up: Hacksaw Cut on 10" Diebu Creek – Nun River Pipeline at Oporoma. Picture was taken during Joint Investigation of 26<sup>th</sup> of April 2015.



Close-up: Hacksaw Cut on 10" Diebu Creek – Nun River Pipeline at Oporoma. Picture was taken during Joint Investigation of 26<sup>th</sup> of April 2015.