



Overview: Part of spill impact on Tunu Well6T Flowline Right of Way at Agbidiana. Picture was taken during Joint Investigation of 7<sup>th</sup> March 2015.



Close-up: Tear on Tunu Well6T Flowline at Agbidiana. Picture was taken during Joint Investigation of 16<sup>th</sup> June 2015.