



Overview: Part of spill impact on Opukushi Well34T Flowline Riser Right of Way at Agbidiama/Egbemo-Angalabiri. Picture was taken during Joint Investigation of 6th May 2015.



Close-up: Pinhole leak on Opukushi Well34T Flowline Riser at Agbidiama/Egbemo-Angalabiri. Picture was taken during Joint Investigation of 6th May 2015.