



Overview: Part of spill impact on 10" Diebu Creek – Nun River Pipeline Right of Way at Oporoma. Picture was taken during Joint Investigation of 18th May 2015.



Close-up: Hacksaw cuts on 10" Diebu Creek – Nun River Pipeline at Oporoma. Picture was taken during Joint Investigation of 18th May 2015.