



Overview: Part of spill impact on 6" Obigbo – North Ogale Pipeline Right of Way at Ogale. Picture was taken during Joint Investigation of 6th June 2015.



Close-up: Illegal fitting on 6" Obigbo – North Ogale Pipeline at Ogale. Picture was taken during Joint Investigation of 6th June 2015.