



Overview: Part of spill impact on Nkali Well11 Wellhead Right of Way at Okoroagu. Picture was taken during Joint Investigation of 16th May 2015.



Close-up: Spill point after replacement of Nkali Well 11 wellhead at Okoroagu. Picture was taken during Joint Investigation of 16th May 2015.