


**Overview:** Part of impact observed on Afam Well 25 access road at Afam-Ukwu. Picture was taken during Joint Investigation of 12<sup>th</sup> November 2015.



**Overview:** Part of impact observed on Afam Well 25 access road at Afam-Ukwu. Picture was taken during Joint Investigation of 12<sup>th</sup> November 2015.