


Close-up: Illegal fitting with concrete cap on 28" Nkpoku – Bomu Pipeline at B-Dere. Picture was taken during Joint Investigation of 19<sup>th</sup> November 2015.



Close-up: Illegal fitting exposed on 28" Nkpoku – Bomu Pipeline at B-Dere. Picture was taken during Joint Investigation of 19<sup>th</sup> November 2015.