



Overview: Part of spill impact on Benisede Well3T Wellhead Right of Way at Ojobo. Picture was taken during Joint Investigation of 26<sup>th</sup> November 2015.



Close-up: Former position of Surface Safety Valve (SSV) on Benisede Well3T Wellhead at Ojobo. Picture was taken during Joint Investigation of 26<sup>th</sup> November 2015.