




Overview: Part of spill impact around Agbada1 Well50 at Omuchi. Picture was taken during Joint Investigation of 24th November 2015.



Close-up: Former position of mutiple valves removed from Agbada1 Well50 at Omuchi. Picture was taken during Joint Investigation of 24th November 2015.