



Close-up: Illegal fitting enclosed with concrete on 28" Nkpoku-Bomu Pipeline at B-Dere. Picture was taken during Joint Investigation of 21st November 2015.



Close-up: Illegal fitting with concrete removed on 28" Nkpoku-Bomu Pipeline at B-Dere. Picture was taken during Joint Investigation of 21st November 2015.