



Overview: Part of spill impact on 20" KoloCreek – Rumuekpe Pipeline Right of Way at Aminigboko. Picture was taken during Joint Investigation of 15<sup>th</sup> October 2015.



Close-up: Failed clamp on 20" KoloCreek – Rumuekpe Pipeline at Aminigboko. Picture was taken during Joint Investigation of 15<sup>th</sup> October 2015.