


**Overview:** Part of spill impact on 36" Nkpoku-Bomu Pipeline Right of Way at Atali. Picture was taken during Joint Investigation of 20<sup>th</sup> October 2015.



**Close-up:** Illegal fitting on 36" Nkpoku-Bomu Pipeline at Atali. Picture was taken during Joint Investigation of 20<sup>th</sup> October 2015.