



Overview: Part of spill impact on 6" Yokri Manifold1 Disused Flowline to Cluster 95 Right of Way at Obotobo. Picture was taken during Joint Investigation of 17th October 2015.



Close-up: Cut section of missing flowline on 6" Yokri Manifold1 Disused Flowline to Cluster 95 at Obotobo. Picture was taken during Joint Investigation of 17th October 2015.