




Overview: Part of spill impact on 20" Otumara – Escravos Pipeline Right of Way at Ugboegungun. Picture was taken during Joint Investigation of 29th October 2015.



Close-up: Illegal fitting on 20" Otumara – Escravos Pipeline at Ugboegungun. Picture was taken during Joint Investigation of 29th October 2015.